




DIRECT FIT CATALYTIC CONVERTERS
 (888) OBD-2-CAT • www.deccats.com

New Product Announcement

New DEC Part# BMW1466: 1998-1999 BMW M-Roadster 3.2L
 1999 BMW M-Coupe 3.2L



Diversified Environmental Catalysts


**P0420
P0430
PROBLEMS?**

CHECK THIS FIRST!

- Coolant Temperature
- Closed Loop Status
- FUEL TRIMS

Make certain the ECU has control over the Fuel Injection First!

New DEC Part# FOR20482: 1998-2001 Ford Ranger 2.5L with Federal Emissions
 1998-2001 Mazda B2500 with Federal Emissions





DIRECT FIT CATALYTIC CONVERTERS
(888) OBD-2-CAT • www.deccats.com

New DEC Part# HY1729C: 2003-2007 Hyundai Elantra 2.0L CVVT engine
2006-2008 Hyundai Tiburon 2.0L



New DEC Part# HY1739:

1998-1999 Hyundai Accent 1.5L Front



**Most Common causes of
FALSE converter codes
and REAL converter
failure:**

- Deteriorations of the Upstream Oxygen Sensor
- Carbon Deposits in the Combustion Chamber
- Malfunctioning Fuel Pressure Regulator
- Mass Air Sensor Problems
- Engine Oil Consumption
- Un-metered Air (Vacuum Leaks)
- Injector Problems

**Let us show you how to
NARROW IT DOWN!**

**Diversified Environmental
Catalysts**




DIRECT FIT CATALYTIC CONVERTERS
(888) OBD-2-CAT • www.deccats.com



DIRECT FIT CATALYTIC CONVERTERS
(888) OBD-2-CAT • www.deccats.com

New DEC Part# MIT2423: 1996 Mitsubishi Montero 3.0L


1995-1996 Mitsubishi Montero 3.5L



Save time *and* money

Use the simple step-by-step procedures outlined on the reverse side to eliminate "false" converter codes BEFORE replacing any catalytic converter.


**Let DEC Help you to
MAKE THE RIGHT
DECISION**



You won't get the correct results without the right input.

New DEC Part# SUZ3113:


2004-2005 Suzuki Verona
2.5L Inline 6 (Front)






DIRECT FIT CATALYTIC CONVERTERS
(888) OBD-2-CAT • www.deccats.com

New DEC Part# SUZ3114: 2004-2005 Suzuki Verona 2.5L Inline 6 (Rear)



New DEC Part# TOY3231F: 2004-2006 Toyota Sienna 3.3L Front Exhaust Manifold
2004-2007 Toyota Highlander 3.3L Front Exhaust Manifold
2004-2006 Lexus RX330 3.3L Front Exhaust Manifold



Speak with your sales representative to get our Latest tools. Keep that light off the first time!!



CATALYST BELOW EFFICIENCY




CATALYST BELOW EFFICIENCY?

MAYBE - MAYBE NOT!



CATALYST BELOW EFFICIENCY



HINT: IF THE DOWNSTREAM O2 IS MIMICKING THE UPSTREAM, TRY ARTIFICIALLY ENRICHING THE FUEL MIXTURE. IF THE DOWNSTREAM O2 STABILIZES, THE CONVERTER IS WORKING!



COATED SUBSTRATE



BROKEN



CLEAN

HIGH OIL CONSUMPTION AND THE CONVERTER DOESN'T STAND A CHANCE!



OIL FOULED



FIX IT RIGHT:

- Check in front of the catalytic converter
- Catalytic Converters should NEVER fail
- Converters don't get "USED UP"!

Interpreting Live Data is the ONLY WAY to be sure of the problem!

By definition, Catalyst - Any substance of which a small proportion notably affects the reaction rate of a chemical reaction WITHOUT ITSELF BEING CHANGED OR CONSUMED.